

は大き





FIG. 2B




ISOTHERMIC CRYSTALLIZATION

I. GENERATION OF STOCK SATURATED SOLUTIONS USING

II. DISTRIBUTE STOCK SOLUTIONS/GENERATE MIXTURE

A. ADD EXCESS COMPOUND TO EACH STOCK SOLUTION



- B. THOROUGHLY MIX, FILTER SOLUTIONS TO REMOVE
- III. EXAMINE CRYSTALLINITY BY BIREFRINGENCE II. MONITOR PRECIPITATION (OPTICAL DENSITY) ANY UNDISSOLVED MATERIAL

IV. DIFFERENT CRYSTALS TESTED BY DSC AND TG

IV. TEST CRYSTAL FORMS BY XRPD

FIG. 3A

TEMPERATURE—MEDIATED CRYSTALLIZATION

1. GENERATION OF STOCK SATURATED SOLUTIONS USING

II. TEMPERATURE RAMP DOWNS

A. ADD EXCESS COMPOUND TO EACH STOCK SOLUTION AT VARIOUS TEMPS 80°C, 60°C, 40°C, 20°C, 10°C, 80C STOCK







6/8 ე ე



40C STOCK

20C STOCK

B. THOROUGHLY MIX, FILTER SOLUTIONS TO REMOVE ANY UNDISSOLVED MATERIAL. MAINTAIN ORIGINAL

TEMPERATURE

OC STOCK















EVAPORATIVE CRYSTALLIZATION

- II. CONTROLLED PRESSURE RAMP DOWN (TEMPERATURE I. GENERATION OF STOCK SATURATED SOLUTIONS USING
 - A. ADD EXCESS COMPOUND TO EACH STOCK SOLUTION





FIG. 3C

B. THOROUGHLY MIX, FILTER SOLUTIONS TO REMOVE ANY UN-DISSOLVED MATERIAL, MAINTAIN ORIGINAL TEMPERATURE






FIG.4